



Resurfacing

FRANKFORD AVENUE REPAVING



SOLUTION

This project consists of repaving Frankford Avenue from the bridge to the end of the road.

PROBLEM

This collector road is used primarily by local traffic to access businesses on the north end of the corridor. This section of road is deteriorated, resulting in pavement rutting and cracking.

